



To add the missing DTR structure identified in 11KV GIS survey.

Go To ZPM Tcode in SAP following screen appears.



4th option ***DTRs Identified in GIS Survey***



User has to provide no of Missed DTRs identified in the field at the time of GIS Survey.

 :: Add Missing DTRs identified in GIS Mapping::

Add Missing DTRs	999999999999 - Dummy Work order for adding missing DTRs iden ...	<input checked="" type="checkbox"/> Select
No of DTRs identified	10	
<input data-bbox="595 471 714 505" type="button" value="EDIT"/> <input data-bbox="817 471 952 505" type="button" value="Submit"/>		

Add the DTR by giving the following details:

 :: Add Missing DTRs Identified under GIS Mapping ::

Dummy Work Order Work Order: 999999999999 Desc of Work: No of DTRs Identified: 10 No of DTRs charged: 1	
Missing DTR Details Make: <input type="text" value=""/> Select Capacity: <input type="text" value=""/> Serial No: <input type="text"/> Phase: <input type="text"/>	
Missing Structure Details Structure Code No: <input type="text"/> Predominant Load: <input type="text"/> Land Mark: <input type="text"/> Charging Date: <input type="text"/>	
Feeder Details <input checked="" type="radio"/> Same Section <input type="radio"/> Other Section Feeder Number: <input type="text"/> <input data-bbox="690 1268 809 1298" type="button" value="CREATE"/>	

Note:

- This Process is similar to the Adding of the DTRs under Turnkey. Equipment no will be auto generated.
- If structure already exists in SAP it will not allow to add i.e duplicates will not be allowed it will display the message structure already exists.